STATE OF FLORIDA **DEPARTMENT OF HEALTH COUNTY HEALTH DEPARTMENT PUBLIC SCHOOL INSPECTION REPORT**



1 of 2

Facility Information

Permit Number: 13-51-1367862 Name of Facility: Everglades K-8 Ctr. Address: 8375 SW 16 Street City, Zip: Miami 33155

Type: Public Schools

Owner: Miami-Dade County School Board

Person In Charge: Ramon Garrigo Phone: 305-264-4154

PIC Email: rgarrigo@dadeschools.net

Inspection Information

Purpose: Routine Begin Time: 10:25 AM Inspection Date: 7/22/2021 End Time: 11:55 AM

Additional Information

FEMALES 0 CENSUS 0 MALES 0

This form serves as a "Notice of Non-Compliance" pursuant to section 120.695, Florida Statutes. Items marked below violate one or more of the requirements of Rule 6A-2.0010, of the Florida Administrative Code, Chapter 5, section 5 of the State Requirements for Educational Facilities 2014 (SREF); and sections 453 and 468 of the Florida Building Code 6th Edition (2017). Violations must be corrected within the time period indicated above. Continued operation of this facility without making these corrections is a violation. Failure to correct violations in the time frame specified may result in enforcement action being initiated by the Department of Health.

Violation Markings

	SCHOOL SANITATION	
Ν	1. School Site	

BUILDING CONST/MAINT.

IN 2. Playground, Equip & Athletic Fields* OUT 13. Handwashing Facilities IN 3. Athletic & Playground Equipment

IN 4. Construction

OUT 5. Maintenance & Repair N 6. Lighting Standards

N. T. Heating, Ventilation, A/C StandardsN. S. Natural Ventilation

9. Mechanical Ventilation

SANITARY FACILITIES IN 10. Provided/Accessible/Separation IN 11. Group Toilet Rooms

IN 12. Toilet Facilities

IN 14. Soap Dispensers IN 15. Shower Facilities

IN 16. Showers Water Temperatures WATER SUPPLY

IN 17. Approved Source IN 18. Drinking Fountains

LIQUID WASTE & WASTE WATER

IN 19. Sewage Disposal IN 20. Solid Waste

PEST CONTROL

IN 21. Pest Control SAFETY

IN 22. First Aid Kit

DIAPER CHANGING STATION

RESULT: Satisfactory

Correct By: Next Inspection

Re-Inspection Date: None

NA 23. Sanitizers

NA 24. Changing Station & Mats

NA 25. Hand Sink NA 26. Garbage Can

ANIMAL HEALTH & SAFETY NA 27. Animal Maintenance/Aggressive DORM/RESIDENTIAL FACILITIES

NA 28. Maintenance/Complaint

NA 29. Other

Marking Key: IN = the act or item was observed to meet standards; OUT = the act or item was observed not to meet standards; NO = the act or item was not observed to be occurring at the time of inspection; NA = the act or item is not performed by the facility or not part of the operation

Violation Key: * = 2. Playground, Equipment & Athletic Fields

Inspector Signature:

Client Signature:

Form Number: DH 4030 12/16A 13-51-1367862 Everglades K-8 Ctr.

STATE OF FLORIDA DEPARTMENT OF HEALTH COUNTY HEALTH DEPARTMENT PUBLIC SCHOOL INSPECTION REPORT



2 of 2

General Comments

Satisfactory

No census due to school closure during the summer.

Emailed to: Ramon Garrigo/7-22-2021

Email Address(es): rgarrigo@dadeschools.net; jaybolton@dadeschools.net; jware@dadeschools.net;

Violations Comments

ipalacio@dadeschools.net

Violation #5. Maintenance & Repair

-Repair AC window with PC#1097265 in room #016.

- -Replace ceiling tiles with water damage in the following clasrooms #P-4, #145, and between restrooms #202-A and B.
- -Repair wall where board is located on classroom #127 and #215. Apparently humidity, dry paint, and bubbles on wall were observed.

CODE REFERENCE: 5. Maintenance and Repair. 5(1)(e)8.h SREF. Light fixtures and window surfaces, both inside and outside, shall be kept clean, serviceable, and in good repair at all times. 5(1)(e)8.i. Custodial areas shall be kept clean, safe, and orderly at all times. Custodial equipment shall be in good repair at all times. 5(1)(e)8.j SREF. Building components & finishes shall be kept clean & in good repair.

Violation #13. Handwashing Facilities

-Provide running water at handwashing in the girl restroom #211-A and the boy restroom #217-B.

CODE REFERENCE: 13. Handwashing Facilities. 5(13)(h)1 SREF. Hot and cold water shall be provided in toilet rooms at the lavatory. Hot water temperature shall not exceed 110°F. 468.3.5.7.1 FBC. Handwashing facilities shall be located within or adjoining each toilet room.

Inspection Conducted By: Lucia Gonzalez Melendez (913031)

Inspector Contact Number: Work: (305) 623-3500 ex.

Print Client Name: Everglades K-8 Ctr.

Date: 7/22/2021

Inspector Signature:

Client Signature:

Form Number: DH 4030 12/16A 13-51-1367862 Everglades K-8 Ctr.